Oil Field Environmental Incident Summary

Responsible Party: KODIAK OIL & GAS (USA) INC. **Well Operator:** KODIAK OIL & GAS (USA) INC.

Well Name: ERICKSON 152-103-26-35-2H

Field Name: GLASS BLUFF Well File #: 25032

Date Incident:10/30/2014Time Incident:23:00Facility ID Number:County:MCKENZIETwp:152Rng:103Sec:26Qtr:

Location Description:

Submitted By: Britiny Fabry Received By:

Contact Person: Chuck Zinne

1625 BROADWAY STE 250 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels 10 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/17/2015 Clean Up Concluded: 10/31/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

Water went into containment

Action Taken or Planned:

Sucked water out of containment and drain box. Replaced all stuffing box nuts with vendor product

Wastes Disposal Location: An approved disposal site

Agencies Involved:

Updates

Date: 10/31/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a stuffing box leak, remained on location within the diking according to the report. NDIC retains oversight.